



Strong Enterprises

"The parachute company with imagination"

Division of S.E. Inc.

11236 Satellite Blvd. Orlando, FL 32837

Tel. (407) 859-9317 Fax: (407) 850-6978

www.strongparachutes.com sales@strongparachutes.com

Strong Tandem Recertification Requirements

Equipment Manufactured On or Prior To December 31, 2007

All Dual Hawk Tandem Systems manufactured on or prior to December 31, 2007 are authorized for use for ten years +/- 6 months from date of manufacture, at which point they must be returned to Strong Enterprises or an authorized Strong Enterprises Recertification Center for any required updating and recertification. After the inspection, and if necessary reconditioning of the system, it may be placed back into service for eight more years. At the 18th year from date of manufacture the container/harness, risers and passenger harness will be taken out of service. At the 18th year +/- 6 months from date of manufacture the Master reserve canopy may be recertified once more for an additional 5 years after which it will be taken out of service.

Complete service life of container/Harness & Passenger harness: 18 years + 6 months

Complete service life of Master reserve canopy: 23 years + 6 months

Equipment Manufactured On or After January 1, 2008

All Strong Tandem H/C Systems, Student Harnesses, and Tandem Reserves manufactured on or after to January 1, 2008 are authorized for use for ten years +/- 6 months from date of manufacture, at which point they must be returned to Strong Enterprises or an authorized Strong Enterprises Recertification Center for any required updating and recertification. After the inspection, and if necessary reconditioning of the system, it may be placed back into service for ten more years. This recertification cycle will continue every ten years until the gear is deemed un-airworthy.

Tässä valmistajan ohje uuteen resertifointijärjestelmään siirryttäessä:
(2007 loppuun mennessä valmistetut DHT:t)

”Jos repulle ja/tai oppilasvaljaalle on tehty 8v resertifointi, sen katsotaan korvaavan uuden järjestelmän 10v resertifoinnin. Eli tuolle repulle ja/tai oppilasvaljaalle ei enää tehdä uutta reserttiä 13v kohdalla, vaan se menee 25 hypyn ja vuositarkastuksilla elinkaaren loppuun saakka (18 v). Varavarjolle voi myöntää vielä 5 vuotta lisää, jos se on hyväksyttävässä kunnossa - eli vv pitää lähettää resertifioitavaksi 18 vuoden iässä, mikäli sille halutaan lisääikää.”

Päävarjoja ei enää resertifioida. Niiden käyttöön sovelletaan koulutuskäytössä olevien päävarjojen elinkaarta = 20 vuotta (SIL-ohje). Toki päävarjo voi kulumisen takia tulla tiensä päähän aiemminkin.

Kalustokomitea